Date	Total Time Hrs.	Total Time Min.	Time Since Last Overhaul Hrs.	Time Since Last Overhaul Min.	**Engine Service and Maintenance Record** Installations, Inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins
Brought Forward →					
5-18-2007	215	HRS TOTAL TIME -			COMPLIED WITH AD 2007-16-10 BY DETERMINATION
THAT TURBOCHARGERS WERE INSTALLED PRIOR TO MARCH 20, 2007 NO FURTHER ACTION					
REQUIRED PER PARA (f). END.					Aaron E. Hook AP2466607

September 18, 2007 215.8 hours total time. Drained engine oil. Removed, opened and checked oil filter. No contamination noted. Installed new CH 48108-1 filter and serviced with 8 qts Aeroshell 15W50 oil. Ran engine, leak checks ok. END. Aaron E Hook AP2466607

performance
AIRCRAFT MAINTENANCE
Burlington, North Carolina USA

336-227-1668

Date	Tail #	Serial #	Hobbs	Make	Model
22 Feb 2008	2509W	41061	230.3	Columbia	LC41-550FG

-Completed Engine Annual Inspection IAW Manufactures Inspection Checklists and Maintenance Manuals.
-Differential Compression Test: 1) 76/80 2) 70/80 3) 74/80 4) 74/80 5) 66/80 6) 76/80. Min. psi for day was 44/80.
-Drained oil, removed and inspected oil filter with no defects found. Installed new CH48108-1 Oil Filter and serviced engine with 7qts of Aeroshell 80W. Ground run and leak check good.
-Replaced Induction Air Filter, PN: BA345E.
All ADs have been checked and complied with through this date. This engine was found to be in airworthy condition and is returned to service.

Abner Tisdale
430909064 IA

Abner Tisdale

2/11/09	238	4			

N2509W S/N 41061 Hobbs 238.4 11 Feb 2009

I certify that this engine has been inspected in accordance with Columbia m/m inspection checklist and TCM maintenance and overhaul manual. AD,s were checked for applicability and compliance. See attached listing. The owner operator has been furnished with a list of discrepancies and corrective actions. I certify that this engine was inspected in accordance with an annual inspection and found to be in an airworthy condition.

Michael E. Bassham
A+P298722435IA

Date	Total Time		Time Since Last Overhaul		**Engine Service and Maintenance Record** Installations, Inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins
	Hrs.	Min.	Hrs.	Min.	
Brought Forward →					
					KELLY AEROSPACE N2509W S/N 41061 Hobbs 240.2 11 Feb 2009 Removed and replaced both left and right magnetos and harness with new. Magneto P/N 6320 Left S/N 08081482 Right S/N 08081483. Timed to engine IAW TCM SS0 M/M Ops checks good no defects noted at this time. Mag drop with in tolerance. This action clears CSB08-9A no further action required at this time. P/N of both magneto harness 10-423604-21. Timothy Whitehead A+P 2827008 1625 Lost Nation rd. Willoughby, Ohio 44094 (440) 951-4744